## **Washington Office Location**

21850 88th Place South Kent, WA 98031 Office: (253) 872-2000 Fax: (253) 872-7033



## **Additional Locations**

Eastern Washington: (509) 949-3368 Idaho & Montana: (208) 360-3833 Oregon: (503) 708-9609

## RECONDITIONING A STOKES 61B-MHRR VACUUM BOOSTER







**BEFORE AFTER** 

- Base repair quote supplied to customer prior to receiving the equipment
- Complete visual inspection and disassembly of booster and components
  - Process material present inside booster
  - Contact on non-drive end of rotors and endplates
  - Drive rotor bend on gear fit 0.020"
- Pictures of tear down taken and included in firm quote with detailed description of required repairs
- Firm quote submitted to customer for approval prior to continuance of work
- Complete mechanical and chemical cleaning of all internal components and external surfaces
  - Grind drive rotor to match driven rotor length
  - Surface grind non-drive endplate
  - Balance rotors
  - Bore endplate for oversize stat slinger
  - Installation of new mechanical seal, bearings, gaskets and O-rings
  - Replace drive rotor
  - Replace slinger seal assembly
  - Replace gear assembly
  - Replace oil sight glasses
- Set internal clearances to factory specs
- ▶ 60-minute test run of complete assembly with data acquisition program
- After break-in period has been met, system is helium leak-checked
- Copy of test data acquisition pump down curve included in shipping documents
- Prep, paint and palletize for shipment

