Washington Office Location

21850 88th Place South Kent, WA 98031 Office: (253) 872-2000 Fax: (253) 872-7033



Additional Locations

Eastern Washington: (509) 949-3368 Idaho & Montana: (208) 360-3833 Oregon: (503) 708-9609

RECONDITIONING AN AERZEN GM35S BLOWER







BEFORE

AFTER

- Base repair quote supplied to customer prior to receiving the equipment
- Complete visual inspection and disassembly of blower and components
 - Drive shaft TIR 0.005"
- Pictures of tear down taken and included in firm quote with detailed description of required repairs
- Firm quote submitted to customer for approval prior to continuance of work
- > Complete mechanical and chemical cleaning of all internal components and external surfaces
 - Straighten drive shaft
 - Installation of all new seals, bearings, gaskets, O-rings and sleeves
 - Replace oil sight glasses
- Set internal clearances to factory specs
- 60-minute test run of complete assembly
- Prep, paint and palletize for shipment